

# Request List Report

3/25/2019

FEBRUARY 2019 COMPLETED

3:45 PM

Request #	Category	Address	Status
Created	Problem	Cross Street	
Comments for Work Order			
WANTS DITCH DUG TO KEEP WATER AWAY FROM BACK PATIO. ITS HER FATHERS PLACE.			
19-000103	Public Works	0 HUNTLEY AVE	WO Completed
1/29/2019	Pot Hole Patching		
ROAD EDGES CRUMBLING, AND POT HOLES			
BIG TRUCKS AND HEAVY EQUIPMENT WORKING USES ROAD AS A TURN AROUND			
HUNLTEY-RIFLE-MARLIN			
ROADS NEED OVERLAY			
19-000105	Public Works	0 BROWN RD	WO Completed
1/29/2019	Pot Hole Patching		
SHOULDER EROSION-EBR PLACED LIGHTED BARRICADES ALONG ROAD			
19-000107	Public Works	18418 KEYSTONE AVE	WO Completed
1/31/2019	Backfill/Dressup		
BACK FILL IN YARD			
19-000108	Public Works	0 SAGE DR	WO Completed
2/1/2019	Storm Drain Repair		
SINK HOLES OVER CULVERT ON SIDE OF DRIVEWAY			
19-000112	Public Works	0 FRENCHTOWN RD	WO Completed
2/1/2019	Pot Hole Patching		
POT HOLE FRENCHTOWN RD @ GREENWELL SPRINGS RD			
19-000113	Public Works	0 LOVETT RD	WO Completed
2/1/2019	Miscellaneous		
DUMP TRUCK SPILLED LOAD ON LOVETT NEAR SULLIVAN-CALLED IN			
19-000115	Public Works	10270 MOSS LEA DR	WO Completed
2/4/2019	Backfill/Dressup		
NEEDS DIRT BACKFILL NEXT TO DRIVEWAY			
19-000118	Public Works	0 HUNTLEY AVE	WO Completed
2/4/2019	Miscellaneous		
NEED BARRICADES @ BRIDGE ON END OF HUNTLEY			
19-000119	Public Works	0 PECOS AVE	WO Completed
2/4/2019	Pot Hole Patching		
POT HOLE ENTIRE SUBDIVISION			
PECOS @ CONESTOGA			
CONESTOGA @ PRAIRIE			
19-000120	Public Works	0 GREYSTONE DR	WO Completed
2/4/2019	Pot Hole Patching		
3 POT HOLES GREYSTONE ENTRANCES AND ALSO ON REDSTONE ENTRANCE			
19-000121	Public Works	0 HOOPER RD	WO Completed
2/5/2019	Traffic Sign Maintenance		
INSTALL TEMP 4-WAY STOP SIGNS AT HOOPER AND SULLIVAN			
19-000122	Public Works	14210 RICHARDSON DR	WO Completed
2/5/2019	Off Road Drainage		
CLEAN AND REMOVE DEBRIS FROM OFF ROAD CANAL			
19-000123	Public Works	0 CHAUMONT AVE	WO Completed
2/5/2019	Pot Hole Patching		
REPAIR CORNERS			
19-000127	Public Works	7231 CONESTOGA DR	WO Completed
2/5/2019	Backfill/Dressup		

## Request List Report

3/25/2019

FEBRUARY 2019 COMPLETED

3:45 PM

Request #	Category	Address	Status
Created	Problem	Cross Street	
Comments for Work Order			
DIRT BACKFILL RUTS IN YARD FROM STORM DRAIN REPAIR			
19-000129	Public Works	12143 PHEASANTWOOD DR	WO Completed
2/5/2019	Backfill/Dressup		
ADDITIONAL FILL DIRT NEEDED AND SMOOTH OUT CLUMPS			
19-000131	Public Works	11741 N MILSTEAD PL	WO Completed
2/5/2019	Backfill/Dressup		
BUILD RETAINING WALL			
19-000133	Public Works	6431 OAK CLUSTER DR	WO Completed
2/6/2019	Pot Hole Patching		
PATCH POT HOLES ENTIRE ROAD			
19-000134	Public Works	0 DENHAM RD	WO Completed
2/6/2019	Litter Control		
LITTER CONTROL DENHAM ROAD FROM TWIN LAKES ENTRANCE TO GREENWELL SPRINGS RD BOTH SIDES			
19-000135	Public Works	0 MONHEGAN AVE	WO Completed
2/6/2019	Pot Hole Patching		
POTHOLE - MONHEGAN @ GRETNA GREEN			
19-000137	Public Works	15126 ASHVILLE AVE	WO Completed
2/6/2019	Storm Drain Repair		
MANHOLE CAVING IN			
REFERRED TO EBR SEWER			
CONFIRMATION #478822			
19-000140	Public Works	14626 BON DICKEY DR	WO Completed
2/7/2019	Draining Maintenance		
expose tail line			
19-000141	Public Works	5115 UNIVERSAL AVE	WO Completed
2/7/2019	Backfill/Dressup		
BACKFILL IN YARD			
19-000146	Public Works	6703 SULLIVAN RD	WO Completed
2/12/2019	Traffic Sign Maintenance		
STREET SIGN IS DOWN AT NORWAY PINE & BASSWOOD. POLE AND SIGN STILL INTACT.			
19-000147	Public Works	6703 SULLIVAN RD	WO Completed
2/12/2019	Traffic Sign Maintenance		
STREET SIGN DOWN AT ASHTON @ CREIGHTON. POLE AND SIGN STILL INTACT			
19-000148	Public Works	10812 LANDFAIR AVE	WO Completed
2/12/2019	Storm Drain Repair		
We repaired the catch basin but it wasn't at the address that was on the work order. It was at 10812 land fair			
19-000149	Public Works	20934 WATSON DR	WO Completed
2/13/2019	Backfill/Dressup		
DRIVEWAY CAVING IN - BACKFILL			
19-000150	Public Works	0 MORGAN MEADOW AVE	WO Completed
2/13/2019	Pot Hole Patching		
POTHOLES-ENTIRE SUBDIVISION			
MORGAN MEADOW @ SAGEFIELD			
MORGAN MEADOW @ JOOR (ON MORGAN MEADOW)			
SEVERAL ALONG SHOECREEK			
19-000154	Public Works	11007 GLENN WATTS RD	WO Completed
2/14/2019	Off Road Drainage		
DITCH ON THE SIDE OF THE HOUSE NEEDS CLEANING. FULL OF LEAVES			

## Request List Report

3/25/2019

FEBRUARY 2019 COMPLETED

3:45 PM

Request #	Category	Address	Status
Created	Problem	Cross Street	
19-000155	Public Works	0 VILLA TRACE AVE	WO Completed
2/14/2019	Pot Hole Patching		
POTHOLES ON ENTIRE STREET			
19-000156	Public Works	9854 TANGLEWOOD DR	WO Completed
2/14/2019	Draining Maintenance		
ROADSIDE DITCH NEEDS TO BE DUG			
19-000159	Public Works	0 PRAIRIE DR	WO Completed
2/18/2019	Traffic Sign Maintenance		
STOP SIGN DOWN - PRAIRIE @ FRONTIER HO SAYS POST ISN'T REPAIRABLE			
19-000160	Public Works	13126 W WATERSIDE DR	Completed
2/19/2019	Storm Drain Repair		
SIDEWALK IS CRACKED WHERE STORM DRAIN IS.  CALL H.O. BACK WITH FINDINGS			
REFERRED TO EBR SEWER			
19-000162	Public Works	0 LARIAT AVE	WO Completed
2/19/2019	Pot Hole Patching		
EASTSIDE-10 POTHOLES WESTSIDE-SAND IS NOT FIXING THE PROBLEM WHERE BUSES RUN.			
19-000163	Public Works	0 FRONTIER DR	WO Completed
2/19/2019	Pot Hole Patching		
POTHOLE - FRONTIER @ TRIPLE B			
19-000165	Public Works	0 LOVETT RD	WO Completed
2/19/2019	Roadside Weed-eating		
WEEDEAT ROUNDABOUT IN FRONT OF MAGNOLIA SQUARE			
19-000168	Public Works	14238 DENHAM RD	WO Completed
2/20/2019	Roadside Mowing		
CUT CORNER LOT HAMPSHIRE @ DENHAM			
19-000169	Public Works	0 SPARKLE DR	WO Completed
2/20/2019	Miscellaneous		
NO SHOULDER AT THE INTERSECTION OF SPARKLE & SULLY. HUGE HOLE STAYS FULL OF WATER. CARS ARE BEING DAMAGED.			
REFERRED BY EBR			
19-000170	Public Works	0 BROWN RD	Completed
2/20/2019	Miscellaneous		
THERE IS A LARGE DIP IN THE ROAD ON BROWN RD CLOSE TO DYER RD RIGHT PASS WHERE THE BLACKTOP WAS RECENTLY PUT IN THE STREET			
REFERRED BY EBR			
CLOSE OUT PER ALAN'S INVESTIGATION			
19-000171	Public Works	0 DEVALD RD	WO Completed
2/20/2019	Pot Hole Patching		
POTHOLE DEVALD @ HOOPER			
19-000173	Public Works	17789 FRENCHTOWN RD	WO Completed
2/21/2019	Litter Control		
10 GARBAGE BAGS DUMPED AT THIS ADDRESS. CALL H.O. IF YOU HAVE TROUBLE SEEING IT.			
19-000176	Public Works	13929 SPANISH OAKS DR	WO Completed
2/21/2019	Pot Hole Patching		
RAMBLING OAKS ENTRANCE - ON THE EXIT SIDE THE SHOULDER OF THE ROAD NEEDS FILLING. CARS CONSTANTLY DRIVING OFF THE ROAD.			

---

**Request List Report**

3/25/2019

FEBRUARY 2019 COMPLETED

3:45 PM

---

Request #	Category	Address	Status
Created	Problem	Cross Street	
Comments for Work Order			
19-000177	Public Works	11007 GLENN WATTS RD	Completed
2/22/2019	Storm Drain Repair		
SINK HOLE AT THE CORNER OF GLENN WATTS AND CAPTAIN BEAUGH			
Referred to EBR Sewer			
19-000183	Public Works	0 BRIDGEPORT DR	WO Completed
2/25/2019	Pot Hole Patching		
POTHOLES ON BRIDGEPORT BETWEEN MORGAN AND LANDMOR			
19-000184	Public Works	0 EMPRESS DR	WO Completed
2/25/2019	Pot Hole Patching		
EMERGENCY REPAIR - EMPRESS AND LANDMOR POT HOLE			
19-000185	Public Works	0 LOVETT RD	WO Completed
2/25/2019	Pot Hole Patching		
POT HOLE IN ROUND-A-BOUT IN FRONT OF MAGNOLIA SQUARE			
19-000194	Public Works	0 WAX RD	WO Completed
2/25/2019	Pot Hole Patching		
POT HOLE ON EDGE OF ROAD NEAR ENTRANCE TO WOODLAND VIEW			
19-000195	Public Works	10457 PEAIRS RD	WO Completed
2/25/2019	Off Road Drainage		
TAIL LINE BACKING UP. DITCH NEEDS TO BE CLEANED.			
19-000205	Public Works	13719 TRIPLE B RD	WO Completed
2/27/2019	Miscellaneous		
PUT BARRICADE OVER SINKHOLE IN FRONT YARD			

---